

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:							
Company	Kit Pappas Manager of Environmental/Engineering						
OGM	Kad Hauskaanas Envisannastal Oniontist III						

Inspection Report

Permit Number:	C0070020		
Inspection Type:	COMPLETE		
Inspection Date:	Tuesday, May 27, 2008		
Start Date/Time:	5/27/2008 9:30:00 AM		
End Date/Time:	5/27/2008 2:00:00 PM		
Last Inspection:	Monday, April 28, 2008		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Partly Cloudy, Temp. 49 Deg. F. InspectionID Report Number: 1651

> Accepted by: jhelfric 6/2/2008

Permitee: HIDDEN SPLENDOR RESOURCES INC Operator: HIDDEN SPLENDOR RESOURCES INC

Site: HORIZON MINE

Address: 3266 S 125 W, PRICE UT 84501

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

1,577.00	Total Permitted
9.50	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

Types of Operations ✓ Federal ✓ Underground State Surface County ☐ Loadout **✓** Fee Processing Other □ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit Condition #1 states that Hidden Splendor Resources will enter their water monitoring information into the electronic database, EDI. This condition is being met.

Inspector's Sig	gnature:
-----------------	----------

Karl Houskeeper, Environmental Scientist III

Date

Tuesday, May 27, 2008

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070020 Inspection Type: COMPLETE

Inspection Date: Tuesday, May 27, 2008

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark		✓	
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓			
4.d	Hydrologic Balance: Water Monitoring	V		✓	
4.e	Hydrologic Balance: Effluent Limitations	V		V	
5.	Explosives	V			
6.	Disposal of Excess Spoil, Fills, Benches	V	✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments	V	V		
8.	Noncoal Waste	V		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues	V			
10.	Slides and Other Damage	✓			
11.	Contemporaneous Reclamation	V			
12.	Backfilling And Grading	V			
13.	Revegetation	✓			
14.	Subsidence Control	V			
15.	Cessation of Operations	✓			
16.a	Roads: Construction, Maintenance, Surfacing	V			
16.b	Roads: Drainage Controls	V			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	V			
19.	AVS Check	✓			
20.	Air Quality Permit	✓		✓	
21.	Bonding and Insurance	✓		✓	
22.	Other	✓		✓	

Permit Number: C0070020 Inspection Type: COMPLETE

Inspection Date: Tuesday, May 27, 2008

Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit C/007/020 was issued effective 10/11/2006 and expires 10/11/2011.

- -Certificate of Insurance policy number 2609456, issued 09/30/2007 and terminates 09/30/2008.
- -UPDES permit UTG040000 (General) UTG040019 (Site Specific) effective 05/01/2008 and expires midnight 04/30/20013.
- -Air Quality permit DAQE-700-70, issued November 7, 2000.
- -SPCC Plan dated June 2006. The Plan is P.E. certified, stamped, signed and dated 6/20/06 by a Utah P.E.

2. Signs and Markers

The mine ID sign was observed at the point of public access to the mine. The sign contained the name of the mine, address, phone number, permit number, and MSHA number.

4.a Hydrologic Balance: Diversions

Mine belting inside the diversion ditch adjacent to the Office/Bathhouse area. Diversion is still functional, material to be removed as soon as possible. Materials need to be kept away form the diversion to avoid compliance action in the future.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The first quarter 2008 and 2007 Annual pond inspection was done on 02/13/2008. No problems were noted

4.d Hydrologic Balance: Water Monitoring

Fourth quarter 2007water monitoring information is in the EDI website but has not been uploaded. Water monitoring is current.

4.e Hydrologic Balance: Effluent Limitations

Reviewed the discharge monitoring reports for January, February, March and April 2008. 001A did not discharge during any of the referenced months. 002A discharged in all of the referenced months, but did not exceed any parameters.

8. Noncoal Waste

Noncoal waste items were in the diversion adjacent to the Office/Bathhouse and on the slope by the undisturbed bypass inlet. Better efforts to maintain the noncoal waste items in designated facilities and to keep the mine site clean is needed to avoid future compliance actions.

20. Air Quality Permit

The Air Quality Permit Approval Order DAQE-700-00 was issued on November 7, 2000. Recent documentation shows the approval order number as DAQP-002-06.

Permit Number: C0070020 Inspection Type: COMPLETE

Inspection Date: Tuesday, May 27, 2008

Page 4 of 4

21. Bonding and Insurance

The bond is secured by a letter of credit through Bank One in the amount of \$57,000 and collateral to add up to the amount of \$342,000. This letter of credit expired on January 20, 2007. The appraisal was updated as of 12/20/06 for the real estate (collateral) and the appraisal is now \$625,000 and the collateral is adequate. The updated reclamation cost estimate is \$445,000 in 2011 dollars.

22. Other

The mine has started a second mining section. Several mine workers vehicles were parked along the side of the county road. The mine needs to evaluate its present and future parking needs to assure adequate parking is available within the permit area. Parking outside of the permit area by mine workers without proper permits can present problems that may lead to enforcement actions.